




Product Highlight..

Product Highlight..



SATURN (TAAT)

Guaranteed Remanufactured Valve Body

1991 & Early 1992 - Part # SAT001

Late 1992 & Up - Part # SAT005

If you're tired of experiencing the classic problems with Saturn TAAT valve bodies, i.e., low line pressure, no reverse, delayed reverse engagement and/or 3rd gear inefficiency...

MEET YOUR NEW ALTERNATIVE!

GUARANTEED Remanufactured Saturn TAAT Valve Bodies by VBXTM!

Saturn TAAT valve bodies typically begin to fail after approximately 70,000 miles of usage. Approximately 75% of their failures can be attributed to excessive wear in the pressure regulator bore due to the continuous oscillation of the valve. The constant oscillation cuts into the bore, leaving a gap that significantly reduces line pressure in the transaxle. After years of R&D, VBXTM designed the ultimate fix for this problem. All contents are removed from the pressure regulator area of the valve body and the bore is reamed on a milling machine with a carbide reamer to guarantee a perfect cut. A new, oversized, VB-XtraTM hardened valve, produced exclusively by VBXTM, is installed, along with new springs designed to tolerate the increased weight of the valve. The fully rebuilt valve body arrives at your location, complete with solenoids that have been digitally tested for integrity & efficiency! It is tested and "ready to go" right out of the package!

*Your time is money! Completing this process yourself could easily cost you more in parts and labor than purchasing a **GUARANTEED Remanufactured Saturn TAAT Valve Body from VBXTM!***

1-866-2GET-VBX

(1-866-243-8829)

www.valvebodyxpress.com

"We Build Them So You Don't Have To."